



Atom Chip Tool Manual

(Support windows 7, windows 10)

1. Please download Atom chip tool software zip file. please compressed the zip file.
<https://www.cthulhumod.com/wp-content/uploads/2020/06/ATOM-Chip-Tools-v1.0.zip>


2. Please double click "ATOM CHIP.exe" to open the software.




3. Please take off battery and hold the fire button, connect Hastur MOD to computer. The software will find your device. please You can release the fire button when the software find your device.

4. If the software finds your device (it will show on the top right), please go to step 5. If not, Please download **Driver booster** (<https://www.iobit.com/en/driver-booster.php>) to scan and update drivers. Please make sure your Hastur MOD connect to computer (the Hastur mod screen show update).


5. You can custom your own logo (80X160 pixel).



6. Reset to default logo.



7. Upgrade firmware.



Any questions, please contact: cs@cthulhumod.com